

# Garbutt Construction Company

REQUEST FOR INFORMATION

P.O. Box 712  
621 Academy Ave  
Dublin, GA 31040

Phone: 478-272-4410  
Fax: 478-275-0642

No. 00030

**TITLE:** Deteriorated Sole Plates

**DATE:** 2/5/2009

**PROJECT:** Renovate/Stabilize Huntington Hall

**JOB:** 1315

**TO:** Attn: Mark W. Nannis  
Nannis & Associates, Inc.

**STARTED:**

**COMPLETED:**

**REQUIRED:** 2/12/2009

## REQUEST:

In an attempt to follow direction provided in RFI 26 (Attached), regarding removing the beams and replacing with new 2x8 walls, we found the existing sole plates for the 1st floor walls to have extensive termite / water damage. In order to replace the sole plate and deteriorated portion of the studs, we propose shoring the load bearing walls as we proposed earlier. Please refer to RFI 21 ( Attached). Once the sole plate and studs are replaced, we intend to continue replacing the beam as you directed. Please advise if this is acceptable.

## ANSWER:

See SC020909-A, developed during site visit on 02-09-09

**Requested By:** Garbutt Construction Company

**Date:** 2/5/2009

**Signed:** \_\_\_\_\_  
Sean Moxley