



**REQUEST FOR INFORMATION  
No. 00041**

**TITLE:** Corners at Dormers  
**PROJECT:** Renovate/Stabilize Huntington Hall  
**TO:** Attn: Joseph Robinson , Jr.  
J W Robinson & Associates

**DATE:** 4/15/2009  
**JOB:** 1315  
**STARTED:**  
**COMPLETED:**  
**REQUIRED:** 4/22/2009

**REQUEST:**

Sheet A2.2 of the drawings show the East dormer to receive new cedar shakes on the sides and the face. The drawings do not call any corner trim for the cedar shakes to terminate into. Without any corner trim, a gap will be left exposed to the elements. Please advise how to proceed.

**ANSWER:**

**Requested By:** Garbutt Construction Company

**Date:** 4/15/2009

**Signed:** \_\_\_\_\_  
Adam McEachern